


BUILDING AND BOUNDARY WALL SAFETY CERTIFICATE
FOR THE YEAR 2021-22

On visual inspection of Kendriya Vidyalaya Army Area Building, there has been no sign of measures structural issues, crack and distress noticed in the structural parts. Therefore, It is certified that Kendriya Vidyalaya Army Area Building and Boundary wall at Lullanagar, Pune is structurally safe for the year FY 2021-22. Subjected to providing continuous maint services of the building and boundary wall. However, it is recommended that structurally audit may be carried out when ever is required.

Station: Pune

Date: 28 Jun 2021


(A K Kashyap)
AE (Civ)
AGE B/R I (S) Pune
for GE (South) Pune

Tele: 6205

Garrison Engineer (South)
No.1 Gen Bhagat Marg
Pune - 411 040


2081/Gen/ /E2

28 Jun 2021

AGE B/R-I (S) Pune

REQUEST TO ISSUE "BUILDING AND BOUNDARY WALL SAFETY CERTIFICATE"

A copy of KV Army Area letter No. 27025/116/Safety Cert./KVAA/2021/109 dt 25 Jun 2021 is fwd herewith to issue the necessary certificate please.



(A K Kashyap)
AE (Civ)
Offg AGE 'Tech'
for GE (South) Pune

Encls: (As above)



पो.बॉक्स ५२०

दूरध्वनी : २५५०१०००

पुणे महानगरपालिका

शिवाजीनगर, पुणे ५.

मुख्य अग्निशमन अधिकारी यांचे कार्यालय,

सेंट्रल फायर स्टेशन, जा. क्र. अशाद/५४४

महात्मा फुले पेठ, दिनांक : २१/५/२१

पुणे-४११ ०४२.


प्रमाणपत्र


संस्थेचे नाव :- केंद्रीय विद्यालय आर्मी एरिया,
डीएडी कॉम्प्लेक्स, वानवडी रेन्ज, लुल्लानगर, पुणे ४०.

संदर्भ :- आपलेकडील दिनांक ०६/०५/२०२१ रोजीचे पत्र.

प्रमाणित करणेत येते की, सदरच्या इमारतीची प्रत्यक्ष जागेवर जाऊन पाहणी केली असता इमारत तळमजला + एक मजले अशी असून राष्ट्रीय इमारत संहिता २००५ नुसार सदर ठिकाणी आवश्यक ती अस्थायी अग्निशमन यंत्रणा बसविण्यात आलेली आहे.

सदरचे प्रमाणपत्र हे संबंधीतांचे मागणी अर्जावरून देण्यात येत असून ते पुढील १ वर्षाकरिता ग्राह्य धरण्यात येईल.


(प्रमोद रा. सोनवणे)
स्टेशन ड्युटी ऑफीसर
अग्निशमन दल, पुणे महानगरपालिका


(प्रशांत स. रणपिसे)
मुख्य अग्निशमन अधिकारी
पुणे महानगरपालिका

WATER SAMPLE FOR BACTERIOLOGICAL EXAMINATION
SHO PUNE-40

WT-28/21
29/1

1. Sample of water collected from : KV (AA) NEAR VIKRAM BATH
2. The exact nature of examination Examination : Bacteriological
3. Date and hour of sampling : 28/01/21 @ 7:30 hrs
4. Nature, source & site of sampling : Tap water
5. Nature & distance of any source an inflow of Pollution appears probable : NA
6. Geological strata likely to affect the water : NA
7. If the source be a well :
 - a. Depth of the water surface
 - b. Staining
 - c. Coping
 - d. Covering
 - e. Strata penetrated
 - f. Method of raising water : NA
8. If stored surface of water, nature of storage : NA
9. Meteorological conditions : Clear
10. Any treatment the water has received :
 - a. Clarification : YES
 - b. Chlorination : YES
 - c. Softening : -
 - d. Boiling : -

Station Pune-40

Date Dec 2020



(Ravi Nimonkar)
Lt Col
Officer Commanding